AD-A032939



WVT-TR-76042



Victor H. Montouri

November 1976



BENET WEAPONS LABORATORY WATERVLIET ARSENAL WATERVLIET, N.Y. 12189

TECHNICAL REPORT

AMCMS No. 3297.06.7484

Pron No. M1-4-A1559-01-M7-M7
DTIC QUALITY INSPECTED &

APPROVED FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacturer(s) in this report does not constitute an official indorsement or approval.

DISPOSITION


Destroy this report when it is no longer needed. Do not return it to the originator.

REPORT DOCUMENTATI	ION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM		
REPORT NUMBER	2. GOVT ACCESSION NO	3. RECIPIENT'S CATALOG NUMBER		
WVT-TR-76042				
. TITLE (and Subtitie)		5. TYPE OF REPORT & PERIOD COVERED		
APPLICATION OF AUTOMATIC DRAFT	TING MACHINE			
		6. PERFORMING ORG. REPORT NUMBER		
. AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(a)		
Victor H. Montouri				
PERFORMING ORGANIZATION NAME AND ADD	RESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS		
Benet Weapons Laboratory Watervliet Arsenal, Waterv		AMCMS No. 3297.06.7484		
SARWV-RT-TP	116t, N.1. 12103	PRON No. M1-4-A1559-01-M7-M		
. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE		
US Army Armament Command		November 1976		
Rock Island, Illinois 6120	01	13. NUMBER OF PAGES		
4. MONITORING AGENCY NAME & ADDRESS(1f dl	fferent from Controlling Office)	54 15. SECURITY CLASS. (of thie report)		
		INCLACCIETED		
		UNCLASSIFIED		
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE		
6. DISTRIBUTION STATEMENT (of this Report)				
Approved for public release;	distribution unlimit	- ad		
Approved for public foreuse,	arranting and the state of the			
7. DISTRIBUTION STATEMENT (of the abstract en	tered in Block 20, if different fro	m Report)		
8. SUPPLEMENTARY NOTES				
Automatic Drafting Machine	ary and identify by block number; Digitize			
Comparator Charts	FORTRAN			
Computer	Interactive Grap	hics		
Data Reduction	NC Verification			
Digital Techniques	Numerical Contro	01		
D. ABSTRACT (Continue on reverse eide if necessa	ry and identify by block number)			
This report is a summary	of applications on	an automatic drafting		
machine utilizing the machine	's drafting, the FOF	RTRAN language, and inter-		
		erfacing is accomplished by		

facing with an interactive graphics system. Interfacing is accomplished by punched tape rather than a direct electronic communication. Some programs

DD 1 FORM 1473 EDITION OF 1 NOV 65 IS OBSOLETE

are included.



ACKNOWLEDGEMENT

The author wishes to thank Mr. David Concordia for his patience and aid while debugging and running the various programs. And more so, for his programming several programs, especially the software modifications necessary for N/C verifications.

Also, thanks to Mr. Richard Haggerty for developing WARP on the Computer Graphics System and Mr. William Lorenson for interfacing the two systems, i.e., the ADM and CGS.

TABLE OF CONTENTS

187	Page		
Report Documentation Page, DD Form 1473			
Acknowledgement	i		
Statement of the Problem			
Background and Introduction			
Approach to the Problem	3		
Conclusions	23		
Appendix A: Computer Program to Produce Cam Path Drawings	24		
Appendix B: Linear Regression Analysis Program	26		
Appendix C: Computer Program to Draw Rifling Broach Comparator Charts	34		
Appendix D: Computer Program to Draw Cutter Form Comparator Charts	37		
Appendix E: Computer Program to Draw Gear Tooth Profiles	40		
Appendix F: Computer Program to Draw Vu-Graph Titles or Headings	43		
Distribution List			
LIST OF ILLUSTRATIONS			
Figure			
1. General Cam Path Drawing	5		
2. Sample Data Plot with Regression Line	7		
3. Broach Teeth Comparator Chart for the 105mm M68 Gun Tube	9		
4. Cutter Form Tool Comparator Chart for the 152mm M81 Gun Tube	10		
5. Gear Teeth Profiles for the 20mm Torsion Bar	12		
6. Example of Vu-Graph Application	13		
7. Example of Vu-Graph Application	14		

LIST OF ILLUSTRATIONS (cont)

		Page
Fig	rure	
8.	Computer Graphics System Reproduction	16
9.	WARP Chart	17
10.	N/C Verification - Center Line of Cutting Tool Path	19
11.	Extractor	22
	LIST OF TABLES	
Tab	le	
1.	Regression Analysis Terminal Output	6
2.	N/C Machines Verified on the ADM	20

STATEMENT OF THE PROBLEM

To achieve the maximum usage of the automatic drafting machine (ADM), it was essential that software be developed to meet the requirements of this installation. This project effort was to focus on the development of software needed to enhance the ADM capabilities. This was simultaneously accompanied with a program to develop procedures for digitizing existing drawings of components, tools, and inspection devices. Numerical control (N/C) tapes that are produced by N/C parts programmer had required verification by actually machining a component. Under this project a process was to be developed for the verification and the production of N/C tapes directly from the drawings on the ADM. BACKGROUND AND INTRODUCTION

An ADM was procured from the Gerber Scientific Instruments Co.

The ADM is comprised of three units: the Series 2000 control, the operator's desk, and the Model 75 table.

The Series 2000 control consists of four (4) major components, namely: a digital computer for control; a hardware interface for electrically matching the computer output to the ADM input; computer peripheral devices for data transfer; and a computer program for directing the operation of the system as an automatic drafting machine.

The digital computer incorporated into the Series 2000 control is the Honeywell Model 316 with a 16 bit word length and 8192 words of memory. The Model 75 Table/Series 2000 control interface functions, such as interpolation and acceleration/deceleration, are handled by the control's

computer under program control.

The peripheral devices for data transfer consist of a high speed, photoelectric, punched tape reader for data input (approximately 400 cps), a high speed tape punch for data output (approximately 100 cps) and an ASR-33 teletypewriter for operator/drafting system communication.

The basic drafting program contains many desirable features. The main feature is the "look ahead" capability. The control reads information up to 50 data blocks ahead of that which is being drawn. This enables the system to calculate optimum velocity and acceleration/deceleration values. Thus, drafting speeds up to 500 inches per minute are attainable.

The Model 75 table has a 5' x 8' rubber platen, flat bed for a drawing surface, a vacuum unit for a sectionalized hold down system and an elevation mechanism for ease in viewing larger drawings.

An additional feature of the ADM is the optical line follower with its support equipment and software. Briefly, this feature enables the system to automatically follow and record data (digitize) for a line of any contour. When the drafting and digitizing capabilities are combined, the possible applications of the system from the engineering design stage through the manufacturing process are greatly increased.

One immediate use of the ADM is verifying N/C tapes. The accuracy of every tape produced, prior to the advent of the ADM, was verified on the N/C machine by "cutting" air or the actual component. In many cases of large operations, this required 3-5 hours or longer. On the ADM, it takes only a few minutes for each verification. In addition, corrections

to the tape can be made immediately. With additional software, it will be possible to verify tapes for most of Watervliet Arsenal's N/C machines and to eventually produce N/C tapes directly on the ADM. The importance of these functions increases as the number of N/C machines increases.

Techniques and software were required for simplified production of comparator charts, overlays, template drawings, etc.

APPROACH TO THE PROBLEM

With the installation of the ADM in 1972, attempts at making drawings of a more complex nature on the ADM were made. It was realized that programming of complex geometries was tedious, cumbersome and time consuming. Although additional software could be purchased from the Gerber Scientific Instruments Co., a more specialized software was needed to meet the needs at Watervliet Arsenal. Thus, special purpose software was developed when needed.

Since the Honeywell Computer, which is the control system for the ADM, has its own FORTRAN compiler, it was decided to develop programs in FORTRAN which could be processed directly on the ADM. These programs, although specific in nature, would be general enough in that they could be used repeatedly like any other FORTRAN program. This differs from the drafting language that was supplied with the ADM in that if a configuration is written (programmed) in the drafting language, only that configuration can be drawn. Although variations of the figure can be made, i.e., change in scale, mirror image or combinations thereof, it is still the same configuration. Programming in this fashion

is cumbersome.

With this idea in mind, the thought was to produce as much software as possible to meet Watervliet Arsenal's requirements. As with any new system, many things had to be learned and peculiarities discovered and overcome. The following are some examples of software developed to meet the requirements at Watervliet Arsenal.

Our first attempt at familiarization and testing the idea proved successful in the area of cam path drawing. Cam path drawings formed from analytical data were cumbersome and time consuming for the draftsman to plot manually. A FORTRAN program to process the analytical data into ADM "understandable" data has simplified the task immensely. Not only has the time required to produce a cam path drawing been reduced, but the quality and accuracy has been considerably improved. Figure 1 is a cam path drawing produced from the program in Appendix A.

In the field of statistical analysis, one of the prerequisites for data analysis is the plotting of data points. Several programs have been written to plot data, to plot data and draw a line of best fit of the form $Y = B_0 + B_1 X$, or to plot data and draw the best fit line of the form Y = BX. The line in either case is determined by the method of least squares which is used to calculate the values of the slope (B_1) and Y - intercept (B_0) . Table 1 lists a portion of these values for a sample data set. The listing also contains the predicted value at each data point and the upper and lower confidence limit for each predicted value. The plotted data and line of best fit can be seen in Figure 2. Appendix B contains the listing of the linear regression program for




Figure 1. General cam path drawing.

TABLE 1. REGRESSION ANALYSIS TERMINAL OUTPUT

DATA ENTHY? (ASH-1, HSH-0)0 AVEHAGE STD DEVIATION

X··· 0·438E 02 0·128E 02 Y··· 0·316E 01 0·127E 01 0.127E 01

SLOFE = 0.994E-01 Y-INTERCEFT = -0.119E 01

CORRELATION COEFFICIENT = C.998E OC

OTTLEBATION	COEFFI	CIENI =	0.998E 00				
X 0•783E	S 02	Y 0•673E 01	PHED: 0.659E	01	LCLY 0.640E	UCI 01 0•678	
0.7791	E 02	0.662E 01	0•655E	01	0.636E	01 0.674	4E 01
0•530E	E 02	0.395E 01	0•407E	01	0 • 39 OE	01 0.425	SE 01
0 • 457 E	E 02	0.329E 01	0.335E	01	0.317E	01 0 • 353	3E 01
0 • 449 E	E 02	0.317E 01	0.327E	01	0•309E	01 0.345	SE 01
0 • 416 E	E 08	0.288E 01	0.294E	01	0.276E	01 0 • 312	E 01
0•375E	2 02	0.253E 01	0 • 253E	01	0.236E	01 0.271	E 01
0.632E	02	0.520E 01	0.509E	01	0.491E	01 0.527	E 01
0•482E	02	0.360E 01	0•360E	01	0.342E	01 0•378	E 01
0•427E	202	0.300E 01	0•305E	01	0.287E	01 0.323	E 01
0•399E	02	0.270E 01	0.277E	01	0.260E	01 0.295	E 01
0.624E	02	0.510E 01	0.501E	01	0 • 483E (01 0.519	E 01
0•495E	02	0.370E 01	0•373E	01	0.355E	0.390	E 01
0 • 434E	02	0.310E 01	0.312E	01	0.294E	0 • 330	E 01
0.374E	02	0.560E 01	0.252E	01	0.235E 0	0.270	E 01
0•615E	02	0.500E 01	0.492E	01	0.474E (0 • 510	E 01
0•499E	02	0.380E 01	0 • 377E	01	0.359E 0	0 • 39 41	E 01
0.420E	02	0.300E 01	0.298E	01	0.280E 0	0 • 3161	E 01
0.410E	02	0.290E 01	0.288E	01	0.270E 0	0 • 3061	E 01
0.515E	02	0.400E 01	0•393E (0 1	0.375E 0	0.410	E 01
0.507E	02	0.390E 01	0.385E (01	0•367E 0		
0.829E	02	0.670E 01	0•705E (01	0•685E 0	1 0 • 724E	01
0•400E	02	0.270E 01	0.278E C)1 (0.260E 0		
0•316E	02	0.190E 01	0•195E C)1 (0.177E 0		
0.279E	02	0.150E 01	6 C•158E O)1 (0.140E 0		
							_





Figure 2. Sample data plot with regression line.

the model $Y = B_0 + B_1X + e$ along with the input data and output (drafting language) commands.

In the manufacture of component parts, dimensions must be checked to insure they have been manufactured within drawing specifications. One method for checking is by using comparator machines. Briefly, this machine projects a silhouette of the component upon a screen which has an accurate outline of the component with its maximum and minimum tolerances. This accurate drawing was previously drawn manually at a much larger scale and then photographically reduced and reproduced on a transparent material - mylar or glass. With the introduction of the ADM, these comparator charts are currently being drawn on the ADM. One particular type of comparator chart, which is used regularly, is in the production of broach teeth used in the manufacture of cannon rifling. The procedure, whether done manually or on the ADM, was tedious and time consuming, requiring approximately 16 hours to complete. The program, listed in Appendix C, reduces this task to one which requires less than one hour from broach drawing to finished comparator chart. Figure 3 is an example of a comparator chart for the broach teeth used in the manufacture of a 105mm M68 gun tube.

Similarly, in shaping various contours, as in the manufacture of breech ring sectors on a gun tube, a cutter form tool is used. In general, these tools have similar geometries which make them conducive to writing a general program to aid in the production of comparator charts. Figure 4 is an example of a comparator chart for a tool used on the 152mm M81 gun tube. Appendix D is the listing of the FORTRAN



RIFLING BROACH D6786881-11810 82.5 TO 1 FEB 1976 105HR H86

Broach teeth comparator chart for the 105mm M68 gun tube. Figure 3.




Figure 4. Cutter form tool comparator chart for the 152mm M81 gun tube.

program used to produce the chart.

In drawing gear tooth profiles, the form most commonly used today is the involute profile. The involute is the curve that is formed by the end of a line that is unwound from the circumference of a circle. It is not the intent here to present the theory or mathematics necessary for developing gear profiles. However, by viewing Figure 5, one can appreciate the task involved in obtaining the end result. The heavy lined portion is the "useable" or "physical" gear. The general program is listed in Appendix E and was used to form the gear profile template needed in the production of the 20mm torsion bar.

Numerous special purpose programs were written to assist in the efficiency and versatility of programming for increased utilization of the ADM. Some programs are aids in developing and producing Vu-graphs. These programs reduced the latter task from a few hours down to a few minutes. Two such examples are shown in Figures 6 and 7. Although they are relatively simple in appearance, prior to the programs developed (Appendix F), consideration had to be given to letter size, spacing, etc. If the letter size was not appropriate, reprogramming was necessary (or redrawing if done manually), resulting in wasted effort. With the computer program, a minor change can be made, resulting in acceptable Vu-graphs.

Other FORTRAN programs were extremely beneficial in reducing the time involved in tedious mathematical calculations necessary for programming in the ADM language. Some of these include determining points of tangency, a point of intersection for two circles, a line and a




Figure 5. Gear teeth profiles for the 20mm torsion bar.

Figure 6. Example of vu-graph application,

STATUS OF FUNDING

AUTHORIZED 255,000 EXPENDED 56,857 COMMITTED 11,047

187,096

REMAINING

Figure 7. Example of vu-graph application.

circle, two lines, etc. Each of these was in the form of a main program and also as a subroutine so they could be run alone or as part of another main program.

All of the preceding programs were written in a form acceptable to the ADM control. Another approach was to investigate methods of interfacing the ADM with Watervliet Arsenal's main frame computer, IBM 360, Model 44. Initially, there were no feasible means of interfacing the two systems without the procurement of additional hardware which was beyond the scope of this project. It was not until the Computer Science Office purchased a Lundy Computer Graphics System (CGS) that a breakthrough was made. Since one of the I/O devices on the Lundy was punched tape, and the ADM also operates with punched tape, this was the obvious way to proceed with a minimum cost. Therefore, software was developed which now permits any configuration that can be drawn on the CGS to be drawn on the ADM. Figure 8 is an example which was "drawn" on the CGS and then reproduced on the ADM. Figure 9 is another example of interfacing the two systems. In this case, a WARP (Work and Resources Plan) chart program was written specifically for the CGS as a preliminary step to being drawn on the ADM. WARP charts are created on the CGS from a sketch or a "marked up" WARP which is to be modified. The process, depending upon complexity, requires from 10 minutes to one hour to complete. "Mistakes" may be "erased" easily on the CGS prior to a finished drawing. Thus, this type of computerization releases the draftsmen from the mundane tasks to more technical projects. The "drawing" of WARP charts can now be done with clerical level personnel, thus, con-




Figure 8. Computer graphics system reproduction.




Figure 9. WARP chart.

siderable cost savings will be realized.

Relative to the field of numerically controlled (N/C) machines, the ADM has been an extremely useful tool. Watervliet Arsenal has over 50 N/C machines whose tool movements are directed by commands on punched tape. Prior to the advent of the ADM, N/C tapes were verified directly on the machine for which they were intended. This process was often time consuming and frustrating. Delays were encountered in waiting for a break in production. When a machine was eventually available, the tape was verified by cutting air, then by possibly cutting wood or plastic and then finally, an actual steel component. At each stage when errors were detected, corrections had to be made and the process repeated. Some tapes required up to five or six hours to run through their cycle. Now, with the use of the ADM, instead of cutting air or wood, etc., the center line of the path of the cutting tool is drawn on paper in minutes. Tool movements can be magnified by a change in scale to detect minute errors which could not have been detected until the final component was produced and inspected. Figure 10 represents the path of an N/C tape verified on the ADM.

Since the ADM was installed, over 200 tapes have been verified.

Although the ADM is a versatile machine, tapes for all types of machines and manufacturing applications cannot be verified. The listing in Table 2 is a summary of the various types of N/C machines which can be verified on the ADM. Prior to January 1976, many of those machines listed could be verified but on several of the machines (marked *) problems were encountered, many of which were minor in nature. Using Digital Assembly




Figure 10. N/C verification - centerline of cutting tool path.

TABLE 2. N/C MACHINES VERIFIED ON THE ADM

Wolverine, P&W Vertical Spindle Mill Kearney & Trecker Machining Center Lodge and Shipley Lathe Cincinnati Turning Center Sunstrand Machining Center Omnimi1 Bostomatic Vertical Spindle Mill LeBlond Horizontal Lathe (Tubes) LeBlond CXR - Horizontal Lathe (Small Components) Pratt & Whitney Wolverine - Vertical Spindle Mill Cincinnati Hydrotel - Vertical Spindle Mill Bullard UTL - Vertical Lathe CIM-X 720 - Horizontal Spindle Mill & Drill XLO Chucker-Vertical Lathe *American Lathe *Giddings and Lewis Machining Center

*Verified but with minor problems.

Programming (DAP), modifications were made to the Drafting Language Program which permitted the ADM to now process tapes for those N/C machines. Verification of the few other machines not listed are currently being pursued.

A recently completed contract with RRC International, Inc., forms the initial step to producing N/C tapes directly on the ADM. The software developed by this company permits Watervliet Arsenal to produce an N/C tape for any N/C machine for which an N/C APT post-processor exists. The process is summarized as follows:

- a. An accurate drawing of the part profile is digitized on the ADM.
- b. The resulting tape is then processed on the IBM 360-44 for the requested N/C machine.
 - c. This resulting tape is then used to control an N/C machine.

While this software was being developed, consideration was given to producing N/C tapes on the ADM without using a main frame computer. That is, a component profile was digitized and, with the aid of a parts programmer, machine parameters were entered manually via the teletypewriter unit. The successful machining of the profile shown in Figure 11 was accomplished on a Bostomatic Milling Machine.

Although both contract and in-house efforts have been successful in producing N/C tapes, more work is needed before the ADM can act as an independent supplement to the parts programmer. This will be pursued. However, the use of the ADM for verifying tapes has been accepted as economical by the Arsenal Operations Directorate.




Figure 11. Extractor.

CONCLUSIONS

The preceding accomplishments are representative of the type of automatic drafting applications at Watervliet Arsenal. The problems pertaining to N/C verification have been overcome and those associated with N/C production are in the process of being solved with no real problems in sight.

Since no new drafting languages exist which can help in programming the ADM, the FORTRAN language will continue to be an extremely useful aid in a generalized programming of the ADM. As the need arises, new computer programs will continue to be developed to minimize drafting program efforts and to maximize ADM utilization.

With the advent of the new Computer Graphics System, a whole new realm of computer aided drafting applications has opened for the ADM. As more developments are introduced in the computer graphics field, greater ADM applications are foreseen.

APPENDIX A

COMPUTER PROGRAM TO PRODUCE CAM PATH DRAWINGS

```
\\DIMENSIONJX(5).JY(5)
NNDATAIP,M/1H+,1H-/
\\WHITE(2,17)
17NNFORMAT(1H*)
20\\KEAD(1,1)N
1\\FORMAT(I3)
\\IF(N)2,2,3
3 \times 1 = 1
10\\READ(1,4)A,R
4\\FUHMAT(2F8.0)
NISX=IP
\\ISY=IF
NA=A/180.*3.14159
\\X=R*COS(A)
\\IF(X)13,13,14
13\\I SX=M
14XXY=R*SIN(A)
\\IF(Y) 15, 15, 16
15\\ISY=M
16\\IX=X*1000.
\\IY=Y*1000.
NCALL CONVERCIX, 5, JX)
NCALL CONVER(IY,5,JY)
\\IF(I-1)5,5,6
5\\WRITE(2,7)ISX,JX,ISY,JY
7\\FORMAT(4HGO1X,A1,5A1,1HY,A1,5A1,4HDO2*)
\\I=I+1
NGO TO 10
6\\\\ITE(2,8)|SX,JX,|SY,JY
8\\FORMAT(4HGO1X,A1,5A1,1HY,A1,5A1,4HDO1*)
I = I + 1
\\IF(I-N)10,10,9
9\\\RITE(2,11)
11\\FORMAT(8HD02*M00*)
11G0 TO 20
2\\WHITE(2,12)
12\\FURMAT(4HM30*)
NISTOP
\\END
1150
11
```

APPENDIX A

COMPUTER PROGRAM TO PRODUCE CAM PATH DRAWINGS (cont)

LINEAR REGRESSION ANALYSIS PROGRAM

```
CNN CHAIN JUB-SEG. 1
CNLINEAR REGRESSION (LINREG) PROGRAM-PLOTS DATA POINTS AND LINE
CNOF "BEST FIT." PROGRAM WILL ACCEPT UP TO 50 DATA POINTS.
CNITITLE ALLOWANCE-32 CHARACTERS
CNIX AND Y AXIS LABELS-16CHARACTERS
CNIHE FOLLOWING PARAMETERS ARE NEEDED TO PLOT FOINTS:
C\\(1) SYMBOLS D73, D85 (2) SSM50 5. M51, 12.5 (3) FSNA X13Y13
CNN(4) ICA
NOCOMMON XMIN, XMAX, YMIN, YMAX, X, Y, A, B, N
\\DIMENSION JX(4), JY(4)
\\EQUIVALENCE(IHEAD(1),LABX(1)),(IHEAD(9),LABY(1))
\\DATA MARK/1H*/
CII
CNREAD SAMPLE SIZE, 'T'VALUE
CII
\\WHITE(1,40)
40\\FORMAT(26HDATA ENTRY? (ASR-1, HSR-0))
NREAD(1,41)MASR
41\\FURMAT(I1)
\\IF(MASK.EG.1) GOTO 48
99\\hEAD(2,1)N,T
\\GUTU49
48\\KEAD(1,1)N, T
1\\FOHMAT(I3, F7.0)
CII
CNNREAD GRAPH HEADINGS ND X,Y LABELS
CII
49\\IF(MASR • EQ • 1) GOTO 42
2\\READ(2,3)IHEAD
3\\FORMAT(16A2)
N GO TO 43
42\\READ(1,3) I HEAD
CNIFHINT HEADING, X&Y LABELS
CII
43\\\k\ITE(2,21)
21\\FURMAT(18H*G01X0000Y9000D02*)
\\WRITE(2,22)IHEAD,MARK
22\\FUHMAT(9HM51G56D10,16A2,A1)
NIF(MASH • EQ • 1) GO TO 44
\\READ(2,3)LABX,LAEY
\\G0T045
44\\READ(1,3)LABX,LABY
45\\WRITE(2,23)
23\\FORMAT(18HGO1X-0500Y8300D02*)
NVRITE(2,24) LABY, MARK
24\\FURMAT(6HG56E10,8A2,A1)
\\WRITE(2,25)
25\\FURMAT(18HG01X2000Y-1000D02*)
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

```
\\WRITE(2,26)LABX,MARK
26\\FORMAT(6HG56D10,8A2,A1,4HM00*)
\\XMIN=1.E10
\\XMAX=-1.E10
\\YMIN=1.E10
\\YMAX=-1E10
CII
CNNREAD DATA
CII
\\D0 5 I=1,N
\\IF(MASR.EQ.1)GOTO46
\\READ(2,4)X(I),Y(I)
NNGO TO 47
46\\READ(1,4)X(I),Y(I)
4\\FORMAT(2F10.0)
47\\XMIN=AMIN1(XMIN,X(I))
\\XMAX=AMAX1(XMAX,X(I))
//YMIN=AMINI(YMIN,Y(I))
\\YMAX=AMAX1(YMAX,Y(I))
5\\CONTINUE
CII
CNICALCULATE STATISTICS ON RAW DATA
CII
\\CALL STAT(X,Y,N,T,A,B)
\\CALL CHAIN
NEND
1150
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

```
C
        CHAIN JOB SEG -- 2
$1
    CONTINUE CHAIN
       COMMON XMIN, XMAX, YMIN, YMAX, X, Y, A, B, N
       DIMENSION X(50), Y(50), JX(4), JY(4), TICX(7), TICY(9)
      EQUIVALENCE (X(1), TICX(1)), (Y(1), TICY(1))
      DATA MARK, I P. M/1H*, 1H+, 1H-/
      FLO=A+B*XMIN
      PHI=A+B*XMAX
      DUM=0 .
      IF(PLO.LT.PHI)G0T0300
      DUM=PHI
      PHI=PLO
      FLO=DUM
300
      YMIN=AMINI(YMIN, PLO)
      YMAX=AMAX1(YMAX, PHI)
C
      SCALE DATA TO INCHES((X.XXX)*1000.)&PLOT
C
С
С
      PUNCH DATA FOINTS
C
      DELX=(XMAX-XMIN)/6.
      DELY=(YMAX-YMIN)/8.
      DO 9 I = 1.N
      IX=1000 * (X(I) - XMIN) / DELX
      IY=1000 • * (Y(I) - YMIN) / DELY
      CALL CONVER(IX, 4, JX)
      CALL CONVER(IY, 4, JY)
      WRITE(2,8) JX, JY
8
      FOHMAT(4HGO1X,4A1,1HY,4A1,4HDO2*,10HM50G52D73*)
9
      CONTINUE
С
С
      DRAW AXIS
C
      WRITE(2,11)
11
      FORMAT(17HG01X0000Y8000D02*)
      WRITE(2, 12)
12
      FORMAT(12HG01Y0000D01*)
      WRITE(2,13)
13
      FORMAT(9HG01X6000*)
С
C
      TIC-MARK LABELS
С
      DO 6 I=1.7
      XI = I - 1
      TICX(I) = XMIN + XI * DELX
6
      CONTINUE
      DO 7 I=1.9
      XI = I - 1
      TICY(I)=YMIN+XI*DELY
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

```
7
      CONTINUE
      KEX = 0
      IF(ABS(TICX(1)).LT.ABS(TICX(7)))GOTO200
      XX=ABS(TICX(1))
      GOT065
200
      XX = TICX(7)
65
      IF(XX-10.**KEX)67,66,66
66
      KEX=KEX+1
      GO TO 65
C
C
      X-AXIS LAEELS&TIC MARKS
C
67
      DO 69 I=1,7
      ITIC=(TICX(I)/10.**KEX)*10000.
      IST=IP
      IF(ITIC)80,81,81
80
      IST=M
81
      CALL CONVER(ITIC, 4, JX)
      IM1 = 1000 * (I - 1)
      CALL CONVER(IM1, 4, JY)
      WRITE(2,68) JY, IST, JX
68
      FORMAT(4HGO1X,4A1,16HY-0500D02*G56D10,A1,1H,,4A1,1H*)
      WRITE(2, 70) JY
70
      FORMAT(4HG01X,4A1,16HY0000D02*G52D85*)
69
      CONTINUE
      KEY = 0
      IF(ABS(TICY(1)).LT.ABS(TICY(9)))GOTO201
      XX=ABS(TICY(1))
      GO TO 71
201
      XX = TICY(9)
71
      IF(XX-10.**KEY) 73, 72, 72
72
      KEY=KEY+1
      GO TO 71
С
C
      Y-AXIS LABELS & TIC MARKS
C
73
      DO 75 I=1.9
      ITIC=(TICY(I)/10.**KEY)*10000.
      IST=IP
      IF(ITIC)82,83,83
82
      IST=M
      CALL CONVER(ITIC, 4, JY)
83
      IM1 = 1000 * (I - 1)
      CALL CONVER(IM1,4,JX)
      WRITE(2, 74) JX, IST, JY
74
      FORMAT(10HG01X-1000Y,4A1,10HD02*G56D10,A1,1H.,4A1,1H*)
      WRITE(2,76)JX
76
      FORMAT(9HG01X0000Y,4A1,11HD02*G53D85*)
75
      CONTINUE
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

```
C
C
      PRINT MAGNITUDE OF TIC MARK LAFELS
C
C
      X-AXIS
C
      WRITE(2,77)KEX
      FORMAT(32HG01X3000Y-0300D02*G56D10X10 EXF , I1, 1H*)
77
С
C
      Y-AXIS
C
      WRITE(2, 78) KEY
      FORMAT(32HG01X-1250Y8150D02*G56D10X10 EXP ,I1, 1H*)
78
C
      DRAW PREDICTED LINE
С
C
      IF(DUM • EQ • O • ) GO TO 301
      PLO=PHI
      PHI = DUM
      IYLO=1000.*(PLO-YMIN)/DELY
301
      CALL CONVER(IYLO, 4, JX)
      IYHI=1000.*(PHI-YMIN)/DELY
      CALL CONVER(IYHI, 4, JY)
      WHITE(2, 14) JX
      FORMAT(8HG01X0000, 1HY, 4A1, 4HD02*)
14
      WRITE(2, 15) JY
      FORMAT(8HG01X6000, 1HY, 4A1, 4HD01*)
15
С
      DRAW 8.5 X 11 BORDER
С
C
96
      WRITE(2, 16)
      FORMAT(18HG01X-1750Y9500D02*)
16
       WRITE(2,17)
       FORMAT(13HG01Y-1500D01*)
17
       WRITE(2, 18)
       FORMAT(9HG01X6750*)
18
       WRITE(2, 19)
19
       FORMAT(9HGO1Y9500*)
       WRI TE(2,20)
       FORMAT(10HG01X-1750*)
20
       WRITE(2, 100)
       FORMAT(12HG01X9999D02*)
100
50
       WRITE(2,28)
       FORMAT(4HM30*)
28
       END
       50
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

INPUT

462.0			
-LN M	hUN	1 WO	M
78 • 3	6	73	••
77.9		62	
53•		95	
45.7		29	
44.9		17	
41.6		88	
37.5		53	
63.2		2	
48.2	3 •	6	
42.7	3 • 3 •		
39.9	2.	7	
62.4	5•		
49.5	3 •	7	
43 • 4	3•		
37.4	2.		
61.5	5 •		
49.9	3•		
42•	3 •		
41.	2.		
51.5	4.		
50.7	3•		
82.9	6.		
40•	2•		
	1 •		
27.9	1 •		
26.6		4	
32.5		05	
34·8 45·9	2.	31 21	
36 • 1		39	
31.1		9	
32.7		04	
34.5		23	
33.6		16	
33.9		16	
35.2		25	
37.7		48	
40 • 4		89	
37.		53	
34.1		24	
34.2		26	
49 • 7		83	
39•		76	
36.2		46	
41.		02	
44 • 1	3•	24	

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

OUTPUT (DRAFTING LANGUAGE COMMANDS)

```
*G01X0000Y9000D02*
M51G56D10
                 HUN TWO
G01X-0500Y8300D02*
G56D10M
G01X2000Y-1000D02*
G56D10-LN M
                       *M00*
G01X5509Y7553D02*M50G52D73*
G01X5467Y7397D02*M50G52D73*
G01X2813Y3613D02*M50G52D73*
G01X2035Y2678D02*M50G52D73*
G01X1950Y2508D02*M50G52D73*
GO1X1598Y2097D02*M50G52D73*
G01X1161Y1601D02*M50G52D73*
GO1X3900Y5384D02*M50G52D73*
G01X2301Y3117D02*M50G52D73*
G01X1715Y2267D02*M50G52D73*
G01X1417Y1842D02*M50G52D73*
G01X3815Y5243D02*M50G52D73*
G01X2440Y3259D02*M50G52D73*
G01X1790Y2409D02*M50G52D73*
G01X1150Y1700D02*M50G52D73*
G01X3719Y5101D02*M50G52D73*
G01X2483Y3401D02*M50G52D73*
G01X1641Y2267D02*M50G52D73*
G01X1534Y2125D02*M50G52D73*
G01X2653Y3684D02*M50G52D73*
G01X2568Y3542D02*M50G52D73*
G01X5999Y7510D02*M50G52D73*
GO1X1428Y1842D02*M50G52D73*
G01X0532Y0708D02*M50G52D73*
G01X0138Y0141D02*M50G52D73*
G01X0000Y0000D02*M50G52D73*
G01X0628Y0921D02*M50G52D73*
G01X0873Y1289D02*M50G52D73*
G01X2056Y2564D02*M50G52D73*
G01X1012Y1402D02*M50G52D73*
G01X0479Y0708D02*M50G52D73*
G01X0650Y0906D02*M50G52D73*
G01X0841Y1176D02*M50G52D73*
G01X0746Y1076D02*M50G52D73*
G01X0777Y1076D02*M50G52D73*
G01X0916Y1204D02*M50G52D73*
G01X1182Y1530D02*M50G52D73*
G01X1470Y2111D02*M50G52D73*
G01X1108Y1601D02*M50G52D73*
GO1X0799Y1190D02*M50G52D73*
G01X0809Y1218D02*M50G52D73*
G01X2461Y3443D02*M50G52D73*
G01X1321Y1927D02*M50G52D73*
G01X1023Y1502D02*M50G52D73*
GO1X1534Y2295D02*M50G52D73*
```

LINEAR REGRESSION ANALYSIS PROGRAM (cont)

OUTPUT (DRAFTING LANGUAGE COMMANDS)

GO1X1865Y2607D02*M50G52D73* G01X0000Y8000D02* G01Y0000D01* G01X6000* GO1X0000Y-0500D02*G56D10+.2659* G01X0000Y0000D02*G52D85* GO1X1000Y-0500D02*G56D10+.3598* G01X1000Y0000D02*G52D85* GO1X2000Y-0500D02*G56D10+.4536* G01X2000Y0000D02*G52D85* GO1X3000Y~0500D02*G56D10+.5475* G01X3000Y0000D02*G52D85* G01X4000Y-0500D02*G56D10+.6413* G01X4000Y0000D02*G52D85* GO1X5000Y~0500D02*G56D10+.7351* G01X5000Y000QD02*G52D85* G01X6000Y~0500D02*G56D10+.8290* G01X6000Y0000D02*G52D85* GO1X-1000Y0000D02*G56D10+ • 1399* G01X0000Y0000D02*G53D85* G01X-1000Y1000D02*G56D10+.2105* G01X0000Y1000D02*G53D85* G01X-1000Y2000D02*G56D10+ • 2811* G01X0000Y2000D02*G53D85* G01X-1000Y3000D02*G56D10+.3516* G01X0000Y3000D02*G53D85* GO1X-1000Y4000D02*G56D10+ 4222* G01X0000Y4000D02*G53D85* GO1X-1000Y5000D02*G56D10+ . 4928* G01X0000Y5000D02*G53D85* GO1X-1000Y6000D02*G56D10+.5633* GO1X0000Y6000D02*G53D85* GO1X-1000Y7000D02*G56D10+.6339* G01X0000Y7000D02*G53D85* GO1X-1000Y8000D02*G56D10+.7045* G01X0000Y8000D02*G53D85* GO1X3000Y-0300D02*G56D10X10 EXF 2* GO1X-1250Y8150D02*G56D10X10 EXP 1*

APPENDIX C

COMPUTER PROGRAM TO DRAW RIFLING BROACH COMPARATOR CHARTS

```
CNNPROGRAM TO DRAW HIFLING BROACH COMPARATOR CHART.
CNR1-LARGE RADIUS
CNR2-SMALL RADIUS
CNA-BROACH ANGLE
CNNW-ONE-HALF BROACH WIDTH
CNAC, RCM-MAX AND MIN CORNER RADIUS.
\\COMMON JX(8), JY(8), KX(8), KY(8)
\\DATA IP,M/1H+,1H-/
\\WRITE(2,5)
5\\FORMAT(38H*%FSNAX35Y35*SSM50.267*SFA62.5B62.5*%*)
\\I=0
\\III=0
\\JJ=3
70\\II=0
NREAD(1,2)R1, A, W, RC, RCM, R2
\\IF(III.EQ.O)SC=R1
2\\FURMAT(6F10.0)
\\A=A* • 01745329
\\IF(III.EQ.O)W1=W
50\\J=2
\\BB=R1*100000.
NCALL CONVER(BB,8,JY)
NCALL CONVER(0.8,JX)
\\WRITE(2,3)IP,JX,JY,J
3\\FORMAT(4HGO1X,A1,8A1,1HY,8A1,2HDO,I1,1H*)
\\J=1
\\AA=W1*100000•
\\CALL CONVER(AA,8,JX)
\\WRITE(2,3)IP, JX, JY, J
\\C3=SQRT((R1*R1)-W*W)
\\BB=C3*100000.
\\CC=R1*100000.
\\AA=(W1-W)*100000.
\\CALL CONVER(0.,8,JX)
NCALL CONVER(AA,8,KX)
\\CALL CONVER(BB,8,JY)
NCALL CONVER(CC,8,KY)
NVRITE(2,4) JJ, IP, KX, JY, JX, KY
4\\FORMAT(2HG0,I1,1HX,A1,8A1,1HY,8A1,1HI,8A1,1HJ,8A1,4HD01*)
\\IF(RC • EQ • O • ) GO TO 8 O
30\\IF(A.EQ.O.)GOTO10
\Lambda AA=W/(SIN(A)/COS(A))+C3-RC/SIN(A)
\\BB=(AA*SIN(A))/(R1-RC)
\\BB=AA*COS(A)-(R1-RC)*SQRT(1.-BB*BB)
\\AA=(SIN(A)*BB)
\\GO TO 11
10\\AA=W-RC
11\\BB=AA/SQRT((R1-RC)*(R1-RC)-AA*AA)
\\BB=ATAN(BB)
\\DD=(W-RC*SIN(BB)-AA)*100000.
```

and the second of the second o

grow by water a contract of the state of the

APPENDIX C

COMPUTER PROGRAM TO DRAW RIFLING BROACH COMPARATOR CHARTS (cont)

```
\\CC=(SQRT((R1-RC)*(R1-RC)-AA*AA)+RC*COS(BB))*100000.
\\CALL CONVER(DD,8,JX)
\\CALL CONVER(CC,8,JY)
\\J=2
//WRITE(2,3) IP, JX, JY, J
12\\CC=(CC/100000.-RC*COS(BB)+RC*SIN(A))*100000.
\\DD=(AA+RC*COS(A)-W)*100000.
\\IF(A.EQ.O.)DD=O.
\\AA=(RC*SIN(BB))*100000.
\\EE=(RC*COS(BB))*100000.
\\CALL CONVER(DD,8,JX)
\\CALL CONVER(CC,8,JY)
\\CALL CONVER(AA,8,KX)
\\CALL CONVER(EE,8,KY)
\\WRITE(2,4)JJ,M,JX,JY,KX,KY
\\IF(I.EQ.1)G0T020
NIF(RC . EQ . RCM) GO TO 20
\backslash \backslash I = I + 1
WRP=RC
NARC=RCM
NGO TO 30
20\\AA=1.57079632-A
\\BB=(CC/100000.)+(SIN(AA)/COS(AA))*DD/100000.
NAA=SIN(AA)/COS(AA)
\\IF(II.EQ.1)AA=-AA
//CC=W
\\IF(II.EQ.1)CC=-W
\\CALL CIRLIN(CC, 0., R2, AA, BB, X, Y, XX, YY)
\\IF(YY.GT.Y)X=XX
\\IF(YY.GT.Y)Y=YY
\\J=1
\\X=X*100000•
\\Y=Y*100000.
\\CALL CONVER(X,8,JX)
\\CALL CONVER(Y,8,JY)
//WRITE(2,3)M,JX,JY,J
\\AA=(SQRT(R2*R2-4.*CC*CC))*100000.
\\BB=W*100000.
\\CALL CONVER(AA,8,JY)
\\CALL CONVER(BE,8,JX)
\\CC=ABS(X)+ABS(W*100000.)
\\CALL CONVER(CC,8,KX)
\\CALL CONVER(Y,8,KY)
\\WRITE(2,4)JJ,M,JX,JY,KX,KY
90\\IF(II • EQ • 1) GO TO 40
\\II=II+1
N=AA//
\\JJ=2
\\M=IP
NIP=AA
```

APPENDIX C

COMPUTER PROGRAM TO DRAW RIFLING BROACH COMPARATOR CHARTS (cont)

```
\\IF(I.EQ.1)RC=RP
\\IF(III.EQ.1)RC=O.
V=1//
\\G0T050
40\\IF(III • EQ • 1) GO TO 60
\\III=III+1
\\AA=IP
\\JJ=3
//IP=M
NM=AA
NGO TO 70
80\\CC=1.57079632-A
\\AA=(BB/100000.-(SIN(CC)/CUS(CC))*AA/100000.)
\\AA=((R2-.008-AA)/(SIN(CC)/COS(CC)))*100000.
\\BB=(R2-.008)*100000.
NCALL CONVERGAA, 8, JX)
\\CALL CONVER(BB,8,JY)
\\WRITE(2,3)M,JX,JY,J
NG01090
60\\I=0
\\AA=1:1*100000.
102\\BB=SC*100000.+1600.
\\I = I + 1
\\J=2
\\CALL CONVER(AA,8,JX)
\\CALL CONVER(BB,8,JY)
\\WRITE(2,3)IP,JX,JY,J
\\BB=R2*100000 • - 1600 •
\\CALL CONVER(BB,8,JY)
\\J=1
\\WRITE(2,3)IP,JX,JY,J
\\AA=AA-W1*100000.
\\IF(I • NE • 2) GO TO 101
VII=IP
//IP=M
101\\IF(I • NE • 3) GOTO 102
NISTOP
\\END
1150
11
```

APPENDIX D

COMPUTER PROGRAM TO DRAW CUTTER FORM COMPARATOR CHARTS

```
C
      PROGRAM TO DRAW CUTTER COMPARATOR CHART.
С
      DRAWS WITH SF 10 TO 1.
С
      ANG, ANGM-ANGLE IN DEGREES (MAX, MIN) .
С
      RIAHIM-LARGE HADIUS (MAXAMIN) .
С
      hau, haum-small hadius-upper(max, min)
С
      h2L, h2LM-SMALL HADIUS-LOWER(MAX, MIN)
С
      ALI, ALIM-TOP HADIUS TO BUTTOM (MAX, MIN)
С
      AL, ALM-CENTER TO SHARP CORNER (MAX, MIN)
С
      AL2, AL2M-SHALL CURNER TO OUTSIDE (MAX, MIN).
C
      ITITLE-TITLE
С
      INUM-DHAWING NUMBEH.
      COMMON ITITLE(15), INUM(15), JX(8), JY(8), KX(8), KY(8)
      HEAD(1,1) R1, H2U, H2L, AL, AL1, AL2, ANG
      HEAD(1,1) HIM, H2UM, H2LM, ALM, ALIM, AL2M, ANGM
      READ(1,2) ITITLE, INUM
1
      FUHMAT(7F10.0)
2
      FORMAT(30A2)
      I = 0
      CEN=0.
      WHITE(2,3)
      FORMAT(25H*%FSNAX35Y35*SSM5016.6*%*)
200
      AA=(R1M-CEN)*1000000.
      CALL CONVER(AA,8,JY)
      WHITE(2,4) JY
4
      FORMAT(6HG01XY-,8A1,8HI02*D01*)
      ANG=ANG* • 01745329
      AA=1.57079632-ANG
      S=-SIN(AA)/COS(AA)
      ALY=SCHI(RIM*RIM-AL*AL)-CEN
      EB=ALY
      ALY=k2UM*SIN(ANG)+ALY
      ALX=AL-h2UM*COS(ANG)
      B=-ALY-S*ALX
      AA= HIM+H2UM
      CALL CILLIN(O., CEN, AA, S, E, X, Y, XX, YY)
      IF(X.L1.0.)X=XX
      IF(Y.G1.O.)Y=YY
      AA=AES((Y+CEN)/X)
      (AA) MAIA=HI
      AX=L2UM*COS(1H)
      AY=H2UM*SIN(TH)
      AXX = (X - AX) * 10000000 \bullet
      AYY=(-Y-AY) *1000000.
      AA=k1M*1000000.
      CALL CONVER(AXX,8,JX)
      CALL CONVER(AYY,8,JY)
      CALL CONVER(AA,8,KY)
      WHITE(2,5) JX, JY, KY
5
      FORMAT(4HG03X,8A1,2HY-,8A1,2HIJ,8A1,1H*)
      AYY=(-Y-R2UM)*1000000.
```

APPENDIX D

COMPUTER PROGRAM TO DRAW CUTTER FORM COMPARATOR CHARTS (cont)

```
AX=AX*1000000.
      AY=AY*1000000.
      AA=X*1000000 •
      CALL CONVER(AA,8,JX)
      CALL CONVER(AYY,8,JY)
      CALL CONVER(AX,8,KX)
      CALL CONVER(AY,8,KY)
      WHITE(2,6) JX, JY, KX, KY
      FORMAT(4HGO2X,8A1,2HY-,8A1,1HI,8A1,1HJ,8A1,1H*)
6
      FX=(X+R2UM*COS(ANG))*1000000.
      FY=(-Y-H2UM*SIN(ANG))*1000000.
      AA= h2UM * 1000000 .
      CALL CONVER(FX,8,JX)
      CALL CUNVER(FY,8,JY)
      CALL CONVERGAA, 8, KY)
      WHITE(2,7) JX, JY, KY
7
      FORMAT(4HGO2X,8A1,2HY-,8A1,2HIJ,8A1,1H*)
      IF(R2L • NE • O • ) GO TO 10
      AA=(AL2/(SIN(ANG)/COS(ANG))+EE)*1000000.
      FX = (AL + AL2) * 10000000.
      CALL CUNVER(FX,8,JX)
      CALL CUNVER(AA,8,JY)
      WRITE(2,8) JX, JY
8
      FORMAT(4HGO1X,8A1,2HY-,8A1,1H*)
      GO TO 100
10
      IF(I • NE • 0) GOTO 15
      A=-Y
      B2=k2UM
15
      AMY = (A-B2+AL1M)
      AIY=AMY-R2L
      FX=FX/1000000.
      AKY=AIY+R2L*SIN(ANG)
      FY=FY/1000000.
      AKX=FX+(AKY-FY)*(SIN(ANG)/COS(ANG))
      AMX=(AKX+R2L*CUS(ANG))*1000000.
      AA=AKX*1000000.
      PB=AKY * 1000000.
      CALL CONVER(AA,8,JX)
      CALL CONVER(PB,8,JY)
      WHITE(2,8)JX,JY
      AA=(k2L*COS(ANG))*1000000.
      BE=(R2L*SIN(ANG))*1000000.
      AMY = AMY * 10000000 •
      CALL CONVER(AMX, 8, JX)
      CALL CONVER(AMY,8,JY)
      CALL CONVER(AA,8,KX)
      CALL CONVERGEB, 8, KY)
      WRITE(2,11) JX, JY, KX, KY
11
      FUHMAT(4HG03X,8A1,2HY-,8A1,1HI,8A1,1HJ,8A1,1H*)
```

APPENDIX D

COMPUTER PROGRAM TO DRAW CUTTER FORM COMPARATOR CHARTS (cont)

```
AA = (AL + AL2) * 1000000.
       CALL CUNVER(AA,8,JX)
       WRITE(2, 12) JX
12
       FORMAT(4HGO1X,8A1,1H*)
100
       CEN=H1-H1M
       ANG= ANGM
       k1M=k1
       h2UM=k2U
       H2L=H2LM
       AL 1M=AL1
       AL = ALM
       AL2=AL2M
       I = I + 1
       IF(I.EQ.1)G0T0200
       AA=(K1M-1.)*1000000.
       CALL CONVERGAA,8,JY)
       WHITE(2,4) JY
       AA = (k1M + .8) * 1000000.
       CALL CONVER(AA,8,JY)
       WhITE(2,20) JY
20
       FORMAT(2HY-,8A1,1H*)
       AA=(H1M+.1)*1000000.
       CALL CONVER(AA,8,JY)
       WHITE(2,4) JY
       AA=(AL+AL2)*1000000.
       CALL CONVER(AA,8,JX)
       WHITE(2, 12) JX
       WKITE(2,26)
26
      FORMAT(4HMOO*)
      AA=(k1M+.3)*1000000.
       CALL CONVER(AA,8,JY)
      WHITE(2,21) JY
      FORMAT(15HG01X-00300000Y-,8A1,4HD02*)
21
      WRITE(2,22)ITITLE
22
      FORMAT(9HM50G56D10,15A2,1H*)
      AA = (k1M + \cdot 33) * 1000000 \cdot
      CALL CONVER(AA,8,JY)
      WRI TE(2,21) JY
      WHITE(2,22) INUM
      AA=(R1M+.36)*1000000.
      CALL CONVER(AA,8,JY)
      WHITE(2,21) JY
      WHITE(2,25)
25
      FORMAT(18HG56D10MAG-10 TO 1*)
      STOP
      END
      $0
```

APPENDIX E

COMPUTER PROGRAM TO DRAW GEAR TOOTH PROFILES

```
(8)YL (8)XL (0MMO)//
NREAD(1,5) PD, PA, GAM, BETA, RS, SF, XINC, RI, SPR, FR
5\\FORMAT(10F7.0)
\\DEG= • 01745329
NNPI=3.1415927
\\PA=PA*DEG
\\BETA=BETA*DEG
\\R=PD*COS(PA)/2.
\\T1=0.
\\GD=0.
\\K=0
\\WRITE(2,45)
45\\FORMAT(1H*)
\\N=360./GAM
200\\K=K+1
0 = I//
100\\D=DEG*T1
\\IF(D.EQ.O.)GOTO80
//T=ATAN(D)
NG01090
CNARP-RPRIME
*0=T//08
90\\IF(T)10,20,10
20\\RP=R
\\G0T030
10\\RP=R/COS(T)
NIF(RP.GT.RS) GO TO 70
30\\PHI=T1*DEG-T
CNN90 DEG = PI/2 - 1.5707963 RADIANS.
\\TDUM=(PI+BETA)/2.-PHI-GD
\\X=RP*COS(TDUM)
\\Y=RP*SIN(TDUM)
\\X=X*SF*100000.
\\Y=Y*SF*100000.
\\CALL CONVER(X,8,JX)
\\CALL CONVER(Y,8,JY)
\\IF(I-1)40,50,60
40\\WRITE(2, 15)
15\\FORMAT(4HDO2*)
\\G0T060
50\\WRITE(2,25)
25\\FORMAT(4HD01*)
60\\WRITE(2,35)JX,JY
35\\FORMAT(4HGO1X,8A1,1HY,8A1,1H*)
\backslash \backslash I = I + 1
\times \times T1 = T1 + XINC
\\G0T0100
```

APPENDIX E

COMPUTER PROGRAM TO DRAW GEAR TOOTH PROFILES (cont)

```
70 \ GD = GD + GAM * DEG
\\T1=0.
\\IF(K.LT.N)GOTO200
\\WRITE(2,55)
55//FORMAT(4HM00*)
\\PD=PD/2.
NCALL CIRABS(R.SF)
\\CALL CIRABS(RI,SF)
NCALL CIRABS(RS,SF)
NCALL CIRABS(PD.SF)
WCALL CIRABS(SPR,SF)
NCALL CIRABS(FR,SF)
NISTOP
\\END
1150
11
```

APPENDIX E

COMPUTER PROGRAM TO DRAW GEAR TOOTH PROFILES (cont)

```
CNNTHIS SUBROUTINE WILL DRAW A COMPLETE CIRCLE(CLOCKWISE)
CNNIN FSNAX25Y25 FORMAT STARTING ON THE POSITIVE Y-AXIS.
CNUSES SUBROUTINE CONVER WITH SIGN.
\\SUBROUTINE CIRABS(R, SF)
NIDIMENSION IR(8)
\\DATA M/1H-/, IP/1H+/
\\R=R*100000.*SF
\\CALL CONVER(R,8,IR)
\\WRITE(2, DIR
1\\FORMAT(5HGO1XY,8A1,4HDO2*)
\\D0100K=1,4
\IR(K \cdot EQ \cdot 2 \cdot OR \cdot K \cdot EQ \cdot 3) IR(1) = M
\\IF(K.GT.3)IR(1)=IP
\\IF(K.EQ.1.OR.K.EQ.3)GOTO30
\\WRITE(2,20)IR,IP,(IR(I),I=2,8)
20\\FORMAT(2HXY,8A1,1HI,8A1,1H*)
NNG0T0100
30\\WRITE(2,10)IR,IP,(IR(I),I=2,8)
10\\FORMAT(4HGO2X,8A1,2HYJ,8A1,4HDO1*)
100\\CONTINUE
\\RETURN
\\END
02//
11
```

COMPUTER PROGRAM TO DRAW VU-GRAPH TITLES OR HEADINGS

```
TITLE-THIS PROGRAM WILL CENTER VU-GRAPH TITLES OR HEADINGS
C
          FOR UP TO 40 CHARACTERS AND UP TO 10 LINES.
C
          DRAWING CONCLUDES WITH AN 8.5X11 IN. BORDER.
С
          SAMPLE INPUT:
C
          • 375HANDBOOK OF<(CR)
C
C
          • 500MATHEMATICAL < (CR)
C
          1 •
C
          • 375FUNCTIONS<(CR)
   FIRST FOUR SPACES-LETTER SIZE FOLLOWED BY NARRATIVE( < END
   OF LINE INDICATOR) . NEXT LINE IS SPACING BETWEEN LINES.
С
   DRAFTING PARAMETERS:
   FSNAX23Y23*ORIGIN IS UPPER LEFT CORNER OF BORDER.SFA1B1*>
       COMMON MS(10), SS(10), LTR(10,40), SPACE(10), JX(5), JY(5)
       COMMON IMS(5), XSS(5)
       DATA IARO/1H
       DATA IPL/1H+/, MIN/1H-/, IAST/1H*/
       K=0
200
      K=K+1
      READ(1,1)SS(K),(LTR(K,I),I=1,40)
       WHITE(1,35)
35
       FURMAT(1H)
      READ(1,1) SPACE(K)
       WRITE(1,35)
1
      FORMAT(F4.0, 40A1)
      IF(SPACE(K) . GT . 0 . ) GO TO 200
      SUM=0.
      MS(1)=0
      IC=0
      M = 1
      D010I=1.K
      SUM = SUM + SS(I) + SPACE(I)
      SS(I) = SS(I) / \cdot 015
      IF(I • GT • 1) GO TO 15
45
      IMS(M)=MS(I)
      XSS(M) = SS(I)
      M=M+1
      GO TO 10
15
      I DUM=I-1
12
      IF(SS(I) • EQ • SS(I DUM)) GO TO 9
      I DUM= I DUM- 1
      IF(IDUM) 11, 11, 12
11
      MS(I)=IC+1
      IC=IC+1
      GUTU45
9
      MS(I)=MS(IDUM)
10
      CONTINUE
53
      IF(M-5)51,51,52
51
      IMS(M) = IC + 1
      IC=IC+1
```

COMPUTER PROGRAM TO DRAW VU-GRAPH TITLES OR HEADINGS (cont)

```
XSS(M) = 0
       M=M+1
       G0T053
52
       WHITE(2,4)(IMS(M),XSS(M),M=1,5)
4
       FORMAT(6H*%SSM5, I1, F5.1, 4(2HM5, I1, F5.1), 3H*%*)
       IF(SUM • GT • 6 • 75) GO TO 14
       SUM=(8.5-SUM)/2.+SS(1)*.015
       SUM = SUM * 1000 .
       CALL CONVER(SUM, 5, JY)
       D020I=1.K
       SUMX=0.
      M = 0
60
       M=M+1
       IF(LTR(I,M).EQ.ICA)GOT030
       IF(LTR(I,M) . EQ.IONE) GO TO 30
       IF(LTR(I,M) . EQ.IEYE) GOTO40
       IF(LTH(I,M) . EQ.IPER) GO TO 30
       IF(LTR(I,M) . EQ.IPL) GO TO 50
       IF(LTR(I,M).EQ.MIN)GOTO50
       IF(LTR(I,M).EQ.IARO)GOTO70
       SUMX=SUMX+.015
       G0 T0 60
30
       SUMX=SUMX+ . 007
       GO TO 60
40
       SUMX=SUMX+ • 005
       G0 T0 60
50
       SUMX=SUMX+ · O11
       GO TO 60
70
       LTR(I,M)=IAST
       SUMX = (SUMX - \cdot 005) * SS(I)
       IF(SUMX.GT.8.5)GOTO16
       SUMX=(11.-SUMX)*500.
       IF(I.EQ.1) GOTO80
       SUM=SUM+(SPACE(I-1)+SS(I)*.015)*1000.
       CALL CONVER(SUM, 5, JY)
80
       CALL CONVER(SUMX, 5, JX)
       WRITE(2,2) IPL, JX, MIN, JY
2
       FORMAT(5H*G01X,6A1,1HY,6A1,4HD02*)
       WRITE(2,3)MS(I),(LTR(I,II),II=1,M)
3
       FORMAT(2HM5, I1, 6HG56D10, 40A1)
20
       CONTINUE
       WRITE(2,5)
5
      FORMAT(31HG01XY-08500D02*X11000D01*Y00000)
6
      FORMAT(30H*X00000*Y-08500*X15000D02*M30*)
       GO TO 25
      WRITE(1,7)
14
7
      FORMAT(SHUERT ERR)
       GO TO 25
16
      WRITE(1.8)
8
      FORMAT(8HHORZ ERR)
25
      STOP
      END
                              44
       50
```

COMPUTER PROGRAM TO DRAW VU-GRAPH TITLES OR HEADINGS (cont)

- •3 EFFECT OF CHEMICAL<
- 1 .
- •3 COMPOSITION ON EROSION<
- 1.5
- •3 DR• R• IMAM<

ST

%SSM50 20.0M51 0.0M52 0.0M53 0.0M54 0.0%*
G01X+02950Y-02850D02
M50G56D10EFFECT OF CHEMICAL*
G01X+02550Y-04150D02
M50G56D10C0MPOSITION ON EROSION*
G01X+04160Y-05950D02
M50G56D10DR. R. IMAM*
G01XY-08500D02*X11000D01*Y00000
*X00000*Y-08500*X15000D02*M30*

COMPUTER PROGRAM TO DRAW VU-GRAPH TITLES OR HEADINGS (cont)

```
C
   THIS PROGRAM OUTFUTS STATUS OF FUNDING VU-GRAPH.
  UPPER LEFT CORNER OF BORDER( . 25, . 25)
C
C
   TAFE IS SELF-SUFF. FOR DRAFTING PARAMETERS.
C
   VALUES FOR AUTHORIZED, EXPENDED, COMMITTED, REMAINING
C
   READ(FROM ASR) IN 13A1, DECIMAL OPTIONAL, COMMAS ARE USED, $ NOT USED.
\\COMMON IX(13), JX(5), JY(5)
NDATA IDJEZIHIJH Z
100\\WRITE(2,1)
1\\FORMAT(28H*%FSTAX23Y23*SSM5020M5122*%*)
\\WRITE(2,2)
2//FORMAT(9HGO1XYDO2*)
\\WRITE(2,3)
3\\FORMAT(37HXO26Y-024*M51G56D1OSTATUS OF FUNDING*)
\\WRI TE( 2, 4)
4\\FORMAT(35HG01X02Y-037D02*M50G56D10AUTHORIZED*)
\\WRITE(2,5)
5\\FORMAT(28HG01Y=0445D02*G56D10EXPENDED*)
\\WHITE(2,6)
6\\FORMAT(28HG01Y-052D02*G56D10C0MMITTED*)
\\WRITE(2,7)
7\\FORMAT(29HGO1Y=0595D02*G56D10REMAINING*)
\\YY=2950.
\\D010I=1.4
\\AJ=13.
\\YY=YY+750•
\\DUM=4700.
\\WRITE(1,51)
51\\FORMAT(1H )
NREAD(1,11)IX
\\D030J=1,13
11\\FORMAT(13A1)
\\IF(IX(J) • EQ • I D) DUM=DUM+160 •
\\IF(IX(J) • EQ • IB) GOTO32
V GO TO 30
32\\AJ=J-1
\\J=13
30//CONTINUE
\\DUM=DUM+(13.-AJ)*300.
\\IF(AJ.GT.4.) DUM= DUM+160.
\\IF(AJ.GT.8.) DUM=DUM+160.
\\IF(AJ.GT.12.) DUM=DUM+160.
\\CALL CONVER(DUM, 5, JX)
\\CALL CONVER(YY, 5, JY)
\\WRITE(2,40)JX,JY,IX
40\\FORMAT(4HGO1X,5A1,2HY-,5A1,1OHDO2*G56D10,13A1,1H*)
10//CONTINUE
\\WRITE(2,41)
41\\F0RMAT(47HG01X-0025Y0025D02*X1075D01*Y-0825*X-0025*Y0025*)
\\WRITE(2,42)
42\\FORMAT(11HX15D02*M30*)
\\WRITE( 1, 50)
50\\FORMAT(49HANOTHER UU-GRAPH? PRESS FOR LEADER THEN HIT START)
\\PAUSE
\\G0T0100
                                  46
\\END
1150
```

11

COMPUTER PROGRAM TO DRAW VU-GRAPH TITLES OR HEADINGS (cont)

```
255,000
56,857
11,047
187,096
ANOTHER VU-GRAPH? PRESS FOR LEADER THEN HIT START
FA
```

```
*%F$TAX23Y23*$$M5020M5122*%*
G01XYD02*
X026Y-024*M51G56D10$TATU$ OF FUNDING*
G01X02Y-037D02*M50G56D10AUTHORIZED*
G01Y-0445D02*G56D10EXPENDED*
G01Y-052D02*G56D10C0MMITTED*
G01Y-0595D02*G56D10REMAINING*
G01X06660Y-03700D02*G56D10255,000 *
G01X06960Y-04450D02*G56D1056,857 *
G01X07280Y-05200D02*G56D1011,047 *
G01X06820Y-05950D02*G56D1011,047 *
G01X06820Y-05950D02*G56D10187,096 *
G01X-0025Y0025D02*X1075D01*Y-0825*X-0025*Y0025*
```

WATERVLIET ARSENAL INTERNAL DISTRIBUTION LIST

May 1976

	No. of Copies
COMMANDER	1
DIRECTOR, BENET WEAPONS LABORATORY	1
DIRECTOR, DEVELOPMENT ENGINEERING DIRECTORATE	1
ATTN: RD-AT	1
· RD-MR	1
RD-PE	1
RD-RM	1
RD-SE	1
RD-SP	1
DIRECTOR, ENGINEERING SUPPORT DIRECTORATE	1
DIRECTOR, RESEARCH DIRECTORATE	2
ATTN: RR-AM	ī
RR-C	1
RR-ME	1
	1
RR-PS	1
TECHNICAL LIBRARY	5
TECHNICAL PUBLICATIONS & EDITING BRANCH	2
DIRECTOR, OPERATIONS DIRECTORATE	1
	•
DIRECTOR, PROCUREMENT DIRECTORATE	1
DIRECTOR, PRODUCT ASSURANCE DIRECTORATE	1
PATENT ADVISORS	1

1 copy to each

CDR

US ARMY MAT & DEV READ. COMD

ATTN: DRCRD

DRCRD-TC

DRCRD-W

5001 EISENHOWER AVE

ALEXANDRIA, VA 22304

OFC OF THE DIR. OF DEFENSE R&E

ATTN: ASST DIRECTOR MATERIALS

THE PENTAGON

WASHINGTON, D.C. 20315

CDR

US ARMY TANK-AUTMV COMD

ATTN: AMDTA-UL

AMSTA-RKM MAT LAB

WARREN, MICHIGAN 48090

CDR

PICATINNY ARSENAL

ATTN: SARPA-TS-S

SARPA-VP3 (PLASTICS

TECH EVAL CEN)

DOVER, NJ 07801

CDR

FRANKFORD ARSENAL

ATTN: SARFA

PHILADELPHIA, PA 19137

DIRECTOR

US ARMY BALLISTIC RSCH LABS

ATTN: AMXBR-LB

ABERDEEN PROVING GROUND

MARYLAND 21005

CDR

US ARMY RSCH OFC (DURHAM)

BOX CM, DUKE STATION

ATTN: RDRD-IPL

DURHAM, NC 27706

CDR

WEST POINT MIL ACADEMY

ATTN: CHMN, MECH ENGR DEPT

WEST POINT, NY 10996

CDR

US ARMY ARMT COMD

ATTN: AMSAR-PPW-IR

AMSAR-RD

AMSAR-RDG

ROCK ISLAND, IL 61201

CDR

US ARMY ARMT COMD

FLD SVC DIV

ARMCOM ARMT SYS OFC

ATTN: AMSAR-ASF

ROCK ISLAND, IL 61201

CDR

US ARMY ELCT COMD

FT MONMOUTH, NJ 07703

CDR

REDSTONE ARSENAL

ATTN: AMSMI-RRS

AMSMI-RSM

ALABAMA 35809

CDR

ROCK ISLAND ARSENAL

ATTN: SARRI-RDD

ROCK ISLAND, IL 61202

CDR

US ARMY FGN SCIENCE & TECH CEN

ATTN: AMXST-SD

220 7TH STREET N.E.

CHARLOTTESVILLE, VA 22901

DIRECTOR

US ARMY PDN EQ. AGENCY

ATTN: AMXPE-MT

ROCK ISLAND, IL 61201

CDR

HQ, US ARMY AVN SCH

ATTN: OFC OF THE LIBRARIAN

FT RUCKER, ALABAMA 36362

EXTERNAL DISTRIBUTION LIST (Cont)

1 copy to each

CDR

US NAVAL WPNS LAB CHIEF, MAT SCIENCE DIV

ATTN: MR. D. MALYEVAC

DAHLGREN, VA 22448

DIRECTOR

NAVAL RSCH LAB

ATTN: DIR. MECH DIV

WASHINGTON, D.C. 20375

DIRECTOR

NAVAL RSCH LAB

CODE 26-27 (DOCU LIB.)

WASHINGTON, D.C. 20375

NASA SCIENTIFIC & TECH INFO FAC

PO BOX 8757, ATTN: ACQ BR

BALTIMORE/WASHINGTON INTL AIRPORT ALABAMA 35809

MARYLAND 21240

DEFENSE METALS INFO CEN

BATTELLE INSTITUTE

505 KING AVE

COLUMBUS, OHIO 43201

MANUEL E. PRADO / G. STISSER

LAWRENCE LIVERMORE LAB

PO BOX 808

LIVERMORE, CA 94550

DR. ROBERT QUATTRONE

CHIEF, MAT BR

US ARMY R&S GROUP, EUR

2 copies to each

CDR

US ARMY MOB EQUIP RSCH & DEV COMD

ATTN: TECH DOCU CEN

FT BELVOIR, VA 22060

CDR

US ARMY MAT RSCH AGCY

ATTN: AMXMR - TECH INFO CEN

WATERTOWN, MASS 02172

CDR

WRIGHT-PATTERSON AFB

ATTN: AFML/MXA

OHIO 45433

CDR

REDSTONE ARSENAL

ATTN: DOCU & TECH INFO BR

12 copies

CDR

DEFENSE DOCU CEN

ATTN: DDC-TCA

CAMERON STATION

ALEXANDRIA, VA 22314

BOX 65, FPO N.Y. 09510

PLEASE NOTIFY CDR, WATERVLIET ARSENAL, ATTN: SARWV-RT-TP,

WATERVLIET, N.Y. 12189, IF ANY CHANGE IS REQUIRED TO THE ABOVE.